HABS DC, WASH, 536-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Union Station 50 Massachusetts Avenue, NE Washington District of Columbia HABS No. DC-139

Nos. 2, 4, 5: Photographer not attributed 1974 All other nos.: Jack E. Boucher, Photographer 1968

DC-139-1	GENERAL VIEW, SOUTH FRONT (1968)
DC-139-2	GENERAL VIEW (CLOSER), SOUTH FRONT (1974)
DC-139-3	SOUTH FRONT, MAIN ENTRANCE PAVILION, ELEVATION (1968)
DC-139-4	SOUTH FRONT, MAIN ENTRANCE PAVILION, OBLIQUE VIEW (1974)
DC-139-5	SOUTH FRONT, MAIN ENTRANCE PAVILION, MORE OBLIQUE VIEW (1974)
DC-139-6	SOUTH FRONT, MAIN ENTRANCE PAVILION, EXTREMELY OBLIQUE VIEW (1968)
DC-139-7	WEST SIDE
DC-139-8	DETAIL, WEST END OF MAIN ENTRANCE PAVILION, SHOWING STATUARY AND INSCRIPTION
DC-139-9	DETAIL, EAST END OF MAIN ENTRANCE PAVILION, SHOWING STATUARY AND INSCRIPTION
DC-139-10	DETAIL, MAIN ENTRANCE PAVILION, TYPICAL COLUMN CAPITAL AND SCULPTURE
DC-139-11	DETAIL, SOUTH FRONT, SCULPTURE ATOP ENTRANCE TO WAITING ROOM
DC-139-12	DETAIL, ARCHED CENTRAL ROOF, FROM THE SOUTH
DC-139-13	DETAIL, WEST SIDE, PILASTER CAPITAL
DC-139-14	DETAIL, EAST ARCADE, ELEVATION FROM THE WEST
DC-139-15	DETAIL, EAST ARCADE, OBLIQUE VIEW FROM THE WEST
DC-139-16	DETAIL, TRAIN SHEDS
DC-139-17	DETAIL, TYPICAL HANGING LAMP
DC-139-18	DETAIL, LIGHT STANDARD WITH EAGLE, SOUTH FRONT, WEST WING
DC-139-19	DETAIL, INSCRIPTION AND LIGHT STANDARDS WITH EAGLES, SOUTH FRONT, WEST WING

UNION STATION
HABS No. DC-139 (P. 2
Index to Photographs

DC-139-20	DETAIL, BASE OF FLAG POLE, SOUTH FRONT
DC-139-21	INTERIOR, WAITING ROOM
DC-139-22	INTERIOR, TRAIN CONCOURSE, FROM WEST
DC-139-23	INTERIOR, PRESIDENTIAL WAITING ROOM
DC-139-24	INTERIOR, DETAIL, ENTRANCE TO TRAIN CONCOURSE FROM WAITING ROOM
DC-139-25	INTERIOR, DETAIL, ENTRANCE TO WAITING ROOM FROM TRAIN CONCOURSE
DC-139-26	INTERIOR, DETAIL, TRAIN GATES
DC-139-27	INTERIOR, DETAIL, ENTRANCE TO PRESIDENTIAL WAITING ROOM
DC-139-28	INTERIOR, DETAIL, CEILING OF PRESIDENTIAL WAITING ROOM
DC-139-29	Photocopy of photograph (Courtesy of B. &. O. Railroad) Date unknown, apparently ca. 1915 INTERIOR, WAITING ROOM

HABS DC, WASH 536-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO UNION STATION 50 Massachusetts Avenue, NE Washington District of Columbia HABS No. DC-139

DC-139-1 through DC-139-29 were transmitted to the Library of Congress.

INDEX TO COLOR TRANSPARENCIES

All color xeroxes were made from a duplicate color transparency.

Jack Boucher, Photographer, 1974

DC-139-30 (CT)

GENERAL VIEW (CLOSER), SOUTH FRONT

DC-139-31 (CT)

SOUTH FRONT, MAIN ENTRANCE PAVILION, OBLIQUE VIEW

DC-139-32 (CT)

SOUTH FRONT, MAIN ENTRANCE PAVILION, MORE OBLIQUE VIEW